

# **Release Notes**

**EWS360AP**

**Ver. v3.6.5\_c1.9.30**

## Revision History

Revision	Date	Reason of Changes
v3.6.5_c1.9.30	Sep 27, 2019	Change and fix update

## Change Log

**Notice:** APs upgraded to this version can only be managed by ezMaster/EWS Switch running c1.9 software.

F/W Version	v3.6.5_c1.9.30
Type	Description
New Feature	N/A
Change	<ol style="list-style-type: none"><li>1. Standalone mode supports Mesh.</li><li>2. Manage SSID is disabled at controller mode.</li><li>3. GUI pop-up window to change account/password after first login</li><li>4. Modify traffic log 100/s -&gt; 10/s to avoid kernel panic issue.</li></ol>
Fix	<ol style="list-style-type: none"><li>1. Fix LLDP that caused high latency issue.</li><li>2. Fix fingerprint issue for missing client information.</li><li>3. Chrome IOT issue.</li></ol>