

Release Notes

EWS5912FP

Ver. v1.07.43_c1.9.37

Revision History

Revision	Date	Reason of Changes
v1.07.43_c1.9.37	Mar 22, 2021	Fix update

Change Log

Notice: Must upgrade the ezMaster to v1.0.64_c1.9.62.

F/W Version	v1.07.43_c1.9.37
Type	Description
New Feature	N/A
Change	N/A
Fix	1. Fix the issue that the connected port cannot display correctly in topology view when the ECS switch and EWS switch are in the same network.