

# **Release Notes**

**EAP1250**

**Ver. v3.5.3\_c1.9.04**

## Revision History

Revision	Date	Reason of Changes
V3.5.3_c1.9.04	Dec 18, 2018	Fix update

## Change Log

F/W Version	v3.5.3_c1.9.04
Type	Description
New Feature	N/A
Change	N/A
Fix	1. Enclose fix for CB/Repeater/WDS-STA connection fail when AP's Fast Roaming is enabled.