

Release Notes

EWS355AP

Ver. v3.6.3_c1.9.30

Revision History

Revision	Date	Reason of Changes
v3.6.3_c1.9.30	Aug 8, 2019	Fix update

Change Log

Notice: APs upgraded to this version can only be managed by ezMaster/EWS Switch running c1.9 software.

F/W Version	v3.6.3_c1.9.30
Type	Description
New Feature	N/A
Change	N/A
Fix	Enclose fix to resolve kernel panic issue when traffic log enabled.