



Release Notes

# SkyKey I

## v1.0.57S\_c1.9.55

3<sup>th</sup> July, 2020

This document provides release information for SkyKey I

## Table of contents

<b>Introduction</b>	<b>3</b>
<b>What's New</b>	<b>4</b>
<b>Supported Platforms</b>	<b>5</b>
<b>Legacy Devices</b>	<b>6</b>
<b>Upgrade Information</b>	<b>7</b>
<b>Limitation</b>	<b>7</b>
<b>Fixed Bugs</b>	<b>7</b>

## Introduction

The v1.0.55S will be included bugs fixed issues on SkyKey I.

## What's New?

**This version has been supported the new features as following lists,**

To ensure compliance with SkyKeyl v1.0.57S on new functions including WPA3, bit rate control and Enable/Disable 11ax under 2.4GHz radio, the Access Point f/w should be upgraded to the v3.7.0 or the later version. The legacy models will not be supported the new function.

-----Worked with v1.0.57S, FW version should be upgrade to v3.7.0 or the later version. -----

- **Indoor**

- EWS330AP
- EWS355AP
- EWS357AP (v1/v2/v3)
- EWS377AP (v1/v2/v3)
- EWS385AP
- EWS550AP
- EWS850AP
- EAP1250
- EAP1300(EXT)

- **Outdoor**

- ENS500-ACv2
- ENS500EXT-ACv2
- EnStation5-ACv2
- EnStationACv2
- ENS620EXT
- ENH1350EXT

-----Worked with v1.0.57S, without supporting any new functions for the version.-----

- **Switches**

- EWS2908P
- EWS2910P(v2)
- EWS5912FP
- EWS7928P
- EWS1200-28TFP
- EWS7952P
- EWS7952FP
- ECS1008P
- ECS1112FP
- ECS1528FP
- ECS1552FP

## Legacy Devices

The following devices can be compatible with v1.0.57S, but not supporting new functions.

- EWS300AP
- EWS310AP
- EWS350AP
- EWS360AP
- EWS370AP
- EWS371AP
- EWS500AP
- EWS510AP
- EWS511AP
- EAP1750H
- EAP2200
- ENS500-AC
- ENS500EXT-AC
- EnStation5-AC
- EnStationAC
- ENS610EXT-NVK
- ENH1750EXT
- EWS650AP
- EWS660AP
- EWS860AP
- EWS870AP
- EWS871AP
- ENS202EXTv2

## Upgrade Information

- N/A

## Limitation

Please assure your SkyKey FW version is the v1.0.55S or the later version.

## Fixed bugs

- EWS385AP cannot downgrade firmware to 3.6.x or older if current firmware version is 3.7.x
- If the ssid9 hotspot 2.0 config field is null, correct it to an empty string.
- Apply the following default walled garden when selecting Cloud4Wi in captive portal:  
\*.googleapis.com, \*.googletagmanager.com, \*.gstatic.com, \*.google-analytics.com
- [Bulk Update] Upgrade AP FW via bulk update will pop abnormal GUI
- [Device Config][Uptime] Uptime of APs can not be updated in "Device Config"
- Fix captive portal cloud4Wi does not work issue.
- Fix the issue that managing groups via cloud remote access will fail.

## Known Issues

- N/A

Costa Mesa, California, USA | (+1) 714 432 8668

[www.engeniustech.com](http://www.engeniustech.com)

Markham, Ontario, Canada | (+1) 905 940-8181

[www.engeniustech.com](http://www.engeniustech.com)

Dubai, UAE | (+971) 4 357 5599

[www.engenius-me.com](http://www.engenius-me.com)

Singapore | (+65) 6227 1088

[www.engeniustech.com.sg](http://www.engeniustech.com.sg)

Eindhoven, Netherlands | (+31) 40 8200 888

[www.engeniusnetworks.eu](http://www.engeniusnetworks.eu)

EnGenius®