



Release Notes

SkyKey I

v1.0.55S_c1.9.33

30th May, 2020

This document provides release information for SkyKey I

Table of contents

Introduction	3
What's New	4
Supported Platforms	5
Legacy Devices	6
Upgrade Information	7
Limitation	7
Fixed Bugs	7

Introduction

The v1.0.55S will be included new features and be fixed issues on SkyKey I.

What's New?

This version has been supported the new features as following lists,

1. Bit Rate Control
2. 802.11ax wireless mode enabled/disabled under 2.4GHz radio
3. WPA3 Configuration
4. Device List Refresh
 - A) Default is disabled. Admin c
 - B) an select the update interval as manually, 5 mins, 10mins, 15mins, 20mins, and 30mins.
 - A) The option can be found at system section under Global setting.

To ensure compliance with SkyKeyl v1.0.55S on new functions including WPA3, bit rate control and Enable/Disable 11ax under 2.4GHz radio, the Access Point f/w should be upgraded to the v3.7.0 or the later version. The legacy models will not be supported the new function.

-----Worked with v1.0.55S, FW version should be upgrade to v3.7.0 or the later version. -----

- **Indoor**

- EWS330AP
- EWS355AP
- EWS357AP (v1/v2/v3)
- EWS377AP (v1/v2)
- EWS385AP
- EWS550AP
- EAP1250
- EAP1300(EXT)

- **Outdoor**

- ENS500-ACv2
- ENS500EXT-ACv2
- EnStation5-ACv2
- EnStationACv2
- ENS620EXT
- ENH1350EXT

-----Worked with v1.0.55S, without supporting any new functions for the version.-----

- **Switches**

- EWS2908P
- EWS2910P(v2)
- EWS5912FP
- EWS7928P
- EWS1200-28TFP
- EWS7952P
- EWS7952FP
- ECS1008P
- ECS1112FP
- ECS1528FP
- ECS1552FP

Legacy Devices

The following devices can be compatible with v1.0.55S, but not supporting new functions.

- EWS300AP
- EWS310AP
- EWS350AP
- EWS360AP
- EWS370AP
- EWS371AP
- EWS500AP
- EWS510AP
- EWS511AP
- EAP1750H
- EAP2200
- ENS500-AC
- ENS500EXT-AC
- EnStation5-AC
- EnStationAC
- ENS610EXT-NVK
- ENH1750EXT
- EWS650AP
- EWS660AP
- EWS860AP
- EWS870AP
- EWS871AP
- ENS202EXTv2

Upgrade Information

-

Limitation

Please assure your SkyKey FW version is the v1.0.51S or the later version.

Fixed bugs

-

Known Issues

-

Costa Mesa, California, USA | (+1) 714 432 8668

www.engeniustech.com

Markham, Ontario , Canada | (+1) 905 940-8181

www.engeniustech.com

Dubai, UAE | (+971) 4 357 5599

www.engenius-me.com

Singapore | (+65) 6227 1088

www.engeniustech.com.sg

Eindhoven, Netherlands | (+31) 40 8200 888

www.engeniusnetworks.eu

EnGenius®