Release Notes

EWS377AP

Ver. v3.7.4_c1.9.51

Revision History

Revision	Date	Reason of Changes
v3.7.4_c1.9.51	Apr 24, 2020	New feature, change, and fix update

Change Log

Notice: APs upgraded to this version can only be managed by ezMaster/EWS Switch running c1.9 software.

F/W Version	v3.7.4_c1.9.51
Type	Description
New Feature	1. Support WPA3 2. Support hotspot 2.0 (Beta)
Change	1. Support scanning-radio scheme v2 for background scanning 2. Support captive portal bridge mode architecture v2 3. Re-arrange WMM / DSCP / 802.1p mappings 4. Adjust auto-channel algorithm to avoid multiple AP choosing the same channel. 5. Update controller version to c1.9.51
Fix	1. Fixed AP hang issue when two AX clients sharing data files.