EnGenius®

Release Notes

ezMaster
v1.0.62_c1.9.61

17th February, 2021

This document provides release information for ezMaster

Table of contents

Introduction

The v1.0.62 ezMaster is the latest version of version 1 ezMaster. This version will be supported the new features.

What's New?

This version has been supported the following new functions,

- Support ECS surveillance switch(ECS1528P/ECS1528FP/ECS1552P/ECS1552FP only support for firmware v1.1.47)
    - PD Lifeguard configuration.
    - PoE extended mode support.
    - Continuous PoE reboot configuration.
    - PD Lifeguard delivering port status.
- Project list, account management, inventory list can export as csv file.
- White/black list support up to 256 mac address.

Supported Devices

To ensure compliance with ezMaster v1.0.62 on new functions including WPA3, Hotspot 2.0 and Enable/Disable 11ax under 2.4GHz radio, the Access Point f/w should be upgraded to the v3.7.0 or the later version. The legacy models will not be supported the new function.

-------Worked with v1.0.54, FW version should be upgrade to v3.7.0 or the later version. -----
· **Indoor**
· EWS330AP
· EWS355AP
· EWS357AP (v1/v2/v3)
· EWS377AP (v1/v2/v3)
· EWS385AP
· EWS550AP
· EWS850AP
· EAP1250
· EAP1300(EXT)

· **Outdoor**
· ENS500-ACv2
· ENS500EXT-ACv2
· EnStation5-ACv2
· EnStationACv2
· ENS620EXT
· ENH1350EXT

-------Worked with v1.0.54, without supporting any new functions for the version.-----
· **Switches**
· EWS2908P
· EWS2910P(v2)
· EWS5912FP
· EWS7928P
· EWS1200-28TFP
· EWS7952P
· EWS7952FP
· ECS1008P
· ECS1112FP

- ECS1528FP
- ECS1552FP

Legacy Devices

The following devices can be compatible with v1.0.54, but not supporting new functions.

- EWS300AP
- EWS310AP
- EWS350AP
- EWS360AP
- EWS370AP
- EWS371AP
- EWS500AP
- EWS510AP
- EWS511AP
- EAP1750H
- EAP2200
- ENS500-AC
- ENS500EXT-AC
- EnStation5-AC
- EnStationAC
- ENS610EXT-NVK
- ENH1750EXT
- EWS650AP
- EWS660AP
- EWS860AP
- EWS870AP
- EWS871AP
- ENS202EXTv2

Upgrade Information

· Please assure to use the v1.0.59 to upgrade your ezMaster to v1.0.62.

Limitation

N/A

Fixed bugs

· Fix the issue of sometimes system busy when it managing the switches.

Known Issues

N/A