

Release Notes

EWS310AP

Ver. v3.0.45_c1.8.57

Revision History

Revision	Date	Reason of Changes
v3.0.45_c1.8.57	Nov 15, 2017	Fix update

Change Log

Notice: APs upgraded to this version can only be managed by ezMaster/EWS Switch running c1.8 software.

F/W Version	v3.0.45_c1.8.57
Type	Description
New Feature	N/A
Change	N/A
Fix	1. Fix the issue that guest network become abnormal upon last hot fix update.