

Release Notes

EWS511AP

Ver. v3.5.2_c1.9.04

Revision History

Revision	Date	Reason of Changes
v3.5.2_c1.9.04	Apr 18, 2019	Fix update

Change Log

Notice: APs upgraded to this version can only be managed by ezMaster/EWS Switch running c1.9 software.

F/W Version	v3.5.2_c1.9.04
Type	Description
New Feature	N/A
Change	N/A
Fix	1. Fix Ethernet IOT issue with LG TV.