

Release Notes

EAP1300

Ver. v3.6.7_c1.9.30

Revision History

Revision	Date	Reason of Changes
v3.6.7_c1.9.30	Dec 17, 2019	Change and Fix update

Change Log

F/W Version	v3.6.7_c1.9.30
Type	Description
New Feature	N/A
Change	1. Add RSSI threshold fast handover (fast handover) function back.
Fix	1. Fix the setting cannot be set with country via ezMaster as below: - set country to Ukraine with ETSI. - set country to Kenya, Morocco, or Saudi Arabia with INT.