

Release Notes

EWS1200-52T

Ver. v1.07.37_c1.9.32

Revision History

Revision	Date	Reason of Changes
v1.07.37_c1.9.32	Oct 22, 2019	New feature, change, and fix update

Change Log

Notice: APs upgraded to c1.9.x version can only be managed by ezMaster/EWS Switch running c1.9 software.

F/W Version	v1.07.37_c1.9.32
Type	Description
New Feature	1. Support bit rate control
Change	1. Update CAPWAP version to c1.9.32 2. System will reboot when memory is less than 10%
Fix	1. Fix the issue that failed to add or delete MAC list of ACL. 2. Fix the issue that failed to add or delete MAC white list of L2 Isolation