

Release Notes

ECS1008P/ECS1112FP/ECS1128FP/ECS1152FP

Ver. v1.1.40

Revision History

Revision	Date	Reason of Changes
V1.1.40	Oct 26, 2020	New feature, change, and fix update

Change Log

F/W Version	V1.1.40
Type	Description
New Feature	<ol style="list-style-type: none">1. Add Connection Diagnostic page in ECS local web management.2. Add "Extend" link-speed mode in port setting page. (Not supported in multi-G series because it is without 10Mbps-speed.)3. Support 2K static VLAN entries.4. Add "On", "Off" action for Scheduled PoE. (for Cloud)5. Add DHCP snooping / relay features for Cloud Agent. (for Cloud)
Change	<ol style="list-style-type: none">1. Adjust the hybrid service priority for Cloud Agent and WTP process.
Fix	<ol style="list-style-type: none">1. Enclose fix for showing memory usage over 100%2. Enclose fix to display correct topology in ezMaster.3. Enclose fix to indicate correct link speed for switch port in ezMaster.