

# Release Notes

**EWS7928FP**

**Ver. v1.07.43\_c1.9.37**

## Revision History

Revision	Date	Reason of Changes
v1.07.43_c1.9.37	Mar 22, 2021	Fix update

## Change Log

**Notice:** Must upgrade the ezMaster to v1.0.64\_c1.9.62.

F/W Version	v1.07.43_c1.9.37
Type	Description
New Feature	N/A
Change	N/A
Fix	1. Fix the issue that the connected port cannot display correctly in topology view when the ECS switch and EWS switch are in the same network.