

Hotel HARRIS KELAPA GADING

JAKARTA, INDONESIA



Problems:

1. Poor wireless throughput due to low Wi-Fi signal and dead spots
2. Poor Wi-Fi performance due to incorrect placement of the APs
3. No network controller

Project Requirements :

Indoor AP with controller for monitoring process, troubleshooting & configuration

EnGenius Solution :

Well planned & deployed EnGenius Indoor APs & Controller Switches via ezMaster Network Management, all with no license or subscription fee.

Products :

307 units of EWS511AP

Wireless Managed Indoor Wall Plate Access Point



21 units of EWS357AP

802.11ax 2x2 Managed Wireless Indoor Access Point

8 units of EWS7952FP

48-Port Managed Gigabit 740W PoE+ Network Switch

1 unit of EWS1200-28TFP

24-Port Managed Gigabit 410W PoE+ Network Switch

