

Release Notes

EWS330AP

Ver. v3.7.20_c1.9.51

Revision History

Revision	Date	Reason of Changes
v3.7.20_c1.9.51	Jul 23, 2021	Fix update

Change Log

Notice: APs upgraded to this version can only be managed by ezMaster/EWS Switch running c1.9 software.

F/W Version	v3.7.20_c1.9.51
Type	Description
New Feature	N/A
Change	N/A
Fix	1. Resolved Fragment and Forge vulnerabilities issue.