

# Release Notes

**EWS377APv1**

**Ver. v3.9.3\_c1.9.51**

## Revision History

Revision	Date	Reason of Changes
v3.9.3_c1.9.51	Dec 27, 2021	Fix update

## Change Log

Notice: APs upgraded to this version can only be managed by ezMaster/EWS Switch running c1.9 software.

F/W Version	v3.9.3_c1.9.51
Type	Description
New Feature	N/A.
Change	N/A
Fix	<ol style="list-style-type: none"><li>1. Fix SNMP get Wi-Fi client list fail.</li><li>2. Fix ezMaster Active Client list (Name/IP/OS) is null.</li><li>3. Fix mesh slave cannot connect to mesh root when L2 isolation is enabled.</li><li>4. Fix XSS vulnerabilities issue for input special SSID.</li><li>5. Fix fragment and forge vulnerabilities issue.</li></ol>