

Release Notes

EWS357APv2

Ver. v3.9.1_c1.9.51

Revision History

Revision	Date	Reason of Changes
v3.9.1_c1.9.51	Sep 27, 2021	Change and Fix update

Change Log

Notice: APs upgraded to this version can only be managed by ezMaster/EWS Switch running c1.9 software.

F/W Version	v3.9.1_c1.9.51
Type	Description
New Feature	N/A.
Change	<ol style="list-style-type: none">1. Update regular domain specification2. Add (DFS) display for channel band2/3 in GUI3. Support telnet setting in GUI4. Support Traditional Chinese language in GUI
Fix	<ol style="list-style-type: none">1. Fix SSH/HTTP Vulnerabilities2. Fix bulk update failed with remote ezM