

Release Notes

EAP1300EXT

Ver. v3.5.2_c1.9.04

Revision History

Revision	Date	Reason of Changes
V3.5.2_c1.9.04	Sep 5, 2018	Change and Fix update

Change Log

F/W Version	v3.5.2_c1.9.04
Type	Description
New Feature	N/A
Change	1. Update CAPWAP version to c1.9.04
Fix	1. Fix L2-isolation doesn't work properly when VLAN enabled.