

Release Notes

EWS2908P

Ver. v1.07.40_c1.9.33

Revision History

Revision	Date	Reason of Changes
v1.07.40_c1.9.33	Apr 7, 2020	Change and fix update

Change Log

Notice: APs upgraded to c1.9.x version can only be managed by ezMaster/EWS Switch running c1.9 software.

F/W Version	v1.07.40_c1.9.33
Type	Description
New Feature	N/A
Change	<ol style="list-style-type: none">1. Update CAPWAP version to c1.9.332. Add force password change rule upon device factory reset.
Fix	<ol style="list-style-type: none">1. Fix one click update state on web is upgrading when ac restart.2. Correct the country name "Moroco" to "Morocco".