

## Release Notes

**EnJet models:**

**ENS500-ACv2**

**ENS500EXT-ACv2**

**EnStation5-ACv2**

**EnStationACv2**

**ENH500v3**

**Ver. v3.7.0\_c1.9.51**

## Revision History

Revision	Date	Reason of Changes
v3.7.0_c1.9.51	May 5, 2020	New Feature, Change and Fix update.

***Remark: Upon f/w upgrade done, please also reset the device to factory default before proceeding to further configuration.***

## Change Log

F/W Version	v3.7.0_c1.9.51
Type	Description
New Feature	<ol style="list-style-type: none"><li>1. Support WPA3.</li><li>2. Support hotspot 2.0 (beta).</li></ol>
Change	<ol style="list-style-type: none"><li>1. Adjust auto-channel algorithm to avoid multiple APs choosing same channel.</li><li>2. Enhancement of small packets drops issue.</li><li>3. Enable STP when EnJet be selected.</li></ol>
Fix	<ol style="list-style-type: none"><li>1. Fixed multicast packets caused IP layer packets drop issue for EnJet mode.</li></ol>