

Release Notes

EWS357

Ver. v3.7.6_c1.9.51

Revision History

Revision	Date	Reason of Changes
v3.7.6_c1.9.51	Aug 21, 2020	New feature, Change and Fix update

Change Log

Notice: APs upgraded to this version can only be managed by ezMaster/EWS Switch running c1.9 software.

F/W Version	v3.7.6_c1.9.51
Type	Description
New Feature	1. Support WPA3. 2. Support hotspot 2.0 beta.
Change	1. Adjust auto-channel algorithm to avoid multiple APs choosing same channel.
Fix	1. Fixed AP hang issue when two AX clients sharing data files.