

Release Notes

EWS377APv3

Ver. v3.8.2_c1.9.51

Revision History

Revision	Date	Reason of Changes
v3.8.2_c1.9.51	Nov 13, 2020	Change and Fix update

Change Log

Notice: APs upgraded to this version can only be managed by ezMaster/EWS Switch running c1.9 software.

F/W Version	v3.8.2_c1.9.51
Type	Description
New Feature	N/A
Change	1. Support Traditional Chinese language.
Fix	1. Fix controller settings with domain name (FQDN) failed. 2. Fix get first DNS wrong problem. 3. Fix captive portal can't redirect to splash page when change ezM public port and captive portal port. 4. Fix MGMT SSID only display 15 minute after reboot the device.