

# Release Notes

**EWS357APv3**

**Ver. v3.8.4\_c1.9.51**

## Revision History

Revision	Date	Reason of Changes
v3.8.4_c1.9.51	Jan 29, 2021	New feature, Change and Fix update

## Change Log

Notice: APs upgraded to this version can only be managed by ezMaster/EWS Switch running c1.9 software.

F/W Version	v3.8.4_c1.9.51
Type	Description
New Feature	1. Support TELNET setting in web GUI.
Change	1. Change MAC Filter list from 32 to 256.
Fix	1. Fixed the syslog timestamp error issue. 2. Fixed the L2 isolation feature in NAT mode.